



XT1000 Quick Start Guide

In order to calibrate your system you will first have to define the scale.
For more detail please see section 3.2 in the user manual.




Turn your XT1000 on and wait until the instrument has fully completed its countdown sequence and the display has stabilised.

If turning on for the first time it is advisable to leave the XT1000 for 30 minutes prior to calibration.

Press both the  and  keys together which will change the display to `120000` with the first `0` flashing.




Pressing the up key  (\blacktriangle), allows you to change each `0` to `1, 2, 3` etc.

Pressing the left  (\blacktriangleleft) and right  (\blacktriangleright) keys then moves you to each position. E.g. `_000`, `2_00`, `28_0`, `280_`.

Change these `0`'s to read `2802` which is the factory access code.



Once you have changed `120000` to read `122802` press the enter  button.


The XT1000 will then briefly display `UnPro` to confirm that the instrument is in the unprotected mode and the parameters can be altered.





Once it has shown `UnPro` the display will change to show to `dEF` (Scale Definition)




XT1000 Quick Start Guide




Press  on **dEF** and you will then see **CAP**, which is the maximum capacity of your scale that you will require.

Press  again and this allows you to input the maximum capacity of your scale using up to 6 digits. You input this number using the ,  and  keys.




Once you have entered your maximum capacity press  to store this value and you should again see **CAP**.


Note: $CAP \div d I \leq 100000$ or you will see **ErrCAP**.



Press  to move to **d I**, which is the division of the scale that you require. This division is determined by taking the **higher** value of:

- CAP (value you have used for the maximum capacity of your scale) \div 100,000
- (Load cell capacity, expressed in the same unit of measure as used for **CAP** \div 10,000) \times $\sqrt{\text{number of load cells}}$
- Maximum product load \div division of the load cell (e.g. 3000 division for a C3 cell.)


Once you have calculated the highest value, press  and using the  or  keys choose the next closest value (rounding up) from 1, 2, 5, 10, 20 or 50. **If you require a number smaller than 1 you can choose the dP (decimal place) in the next step**, for example if 0.05 is required choose 5 in **d I** and then 0.00 in **dP**.

Once you have chosen your division press  to store and you will then again see **d I**.

Note: $CAP \div d I \leq 100000$ or you will see **Errd I**

XT1000 Quick Start Guide







Press  to move to **dP**, which is the position of the decimal point that you require in relation to the capacity of the scale, (for example in a 3000KG scale you may only require 1KG intervals so **0** decimal places)


Press  and choose your **dP** using the  or  keys.

Once you have made your choice press  to store this value and get back to **dP**.







Press  to see **0-t-r-A-C**, which is the level at which the system is automatically zeroed as long as the weight is within the selected band and it is stable.

Press  to choose your required value using the  and  keys.

The default setting is 0.5d. Press  to store this value and get back to **0-t-r-A-C**.








Press  to see **0-t-o-p**, which is the range within which the scale may be zeroed.

Press  to choose your required value, **the default setting is 1.9** but can be altered if required using the  or  key.

Press  to store this value and get back to **0-t-o-p**.








Press  to see **0.5-t-A-r-t**, which zeroes the indicator when it is turned on. Press  and using the  or  keys choose either **off** (which is the default setting recommended for silos/tanks and hoppers), or change to **on** (recommended for platform scales)

Press  to confirm and go back to **0.5-t-A-r-t**.





XT1000 Quick Start Guide



Press  to see **UndErL**, the point at which the computer indicates the input error signal below the minimum range.

Press  and choose your option using the  or  keys, the **default is setting is -oUErL**, once you have chosen your option press  to confirm and go back to **UndErL**.



Press  to see **Un It**, press  to choose your unit of weight using the  and  keys. The options are:

K = Kilogram,


t = Ton,

G = Gram,

Lb = Pound,




o = Ounce,

nonE = None)

Press  to confirm your choice and go back to **Un It**.



The XT1000 scale has now been defined.

By pressing  you will return to **dEF** where pressing either the  or  key and scroll until you see:

CAL 1, to perform a calibration with verified weights. (Section 4.1 in the user manual)

CAL 2, to perform a theoretical calibration if you do not have any verified weights. (Section 4.2 in the user manual)

Pressing  again when you are on **dEF** exits the configuration level completely.

Note: If you exit the configuration level you will have to re-enter the Factory Access Code **2802 to calibrate your XT1000.**



XT1000 Quick Start Guide


CALIBRATION WITH VERIFIED WEIGHTS (CAL 1)


Section 4.1 in the user manual




Ensure that there is no unwanted weight on the system and that you are in the configuration level.

Using the  or  keys scroll from DEF until you see CAL 1.

Press  when you see CAL 1 and you will then see DEr0,

Press  again and you will see the preset coefficient value




Press  again you should see -CAL 1- flashing which will store this as your zero point.

Once it has stored this value it will return to DEr0.



Press  on DEr0 you will see SPAn.




Place your verified weight onto your scale and press  where you will see a value displayed.






XT1000 Quick Start Guide



Ensure that the value shown on the XT1000 matches the weight placed on the scale.

You can alter this value using the ,  and  keys.

Once you have the correct weight showing press  and **-CAL 1-** will again flash storing this value.



Normally this is sufficient for most calibration purposes and at this point you can press  and again  to leave the configuration level completely and your X1000 should now be calibrated and ready to weigh.


XT1000 Quick Start Guide


THEORETICAL CALIBRATION (CAL 2) when no verified weights are available.
Section 4.2 in the user manual




Ensure that there is no unwanted weight on the system and that you are in the configuration level.


Using the  or  keys scroll from DEF until you see CAL 2.

Press  and you will see LCAP.




Press  and enter the nominal capacity of one of the load cells being used.



This value is expressed in the same decimal point used in CAP and d I


Press  to store this value and return to LCAP.



Press  to see Lno, which is the number of load supports.


Please note that all supports must be counted including those without load cells.


Press  to enter the number of supports using the  button.

When correct press  to store this value and you will return to Lno.








XT1000 Quick Start Guide




Press  to see **L5n** which is the mv/v value of the load cell(s) being used. Typically this information is on a sticker on the load cell.


If you have more than one cell in your system then average out the mv/v values and use this average figure.


Press  to enter the mv/v value using the ,  and  keys,



Once correct press  to store this value and you will return to **L5n**.



Press  to see **0E r o** which is your automatic Zero adjustment.

Press the  and you will see the preset coefficient value.

Press  again you should see **-CAL I-** flashing which will store this as your zero point.

Normally this is sufficient for most calibration purposes and at this point you can press  and again  to leave the configuration level completely and your X1000 should now be calibrated and ready to weigh.

